



型号		PS 10				
供应压力	bar	1	2	3	4	5
最大吹气压力	-KPa	0.1	0.2	0.3	0.5	0.7
空气消耗	NI/s	0.5	0.9	1.2	1.6	1.9
吹气量	m ³ /h	5.8	9.2	12.0	14.2	16.2
A		94				
B		118.5				
C		24.5				
R		G3/8"				
重量	Kg	0.49				
型号		PS 14				
供应压力	bar	1	2	3	4	5
最大吹气压力	-KPa	0.1	0.2	0.3	0.5	0.7
空气消耗	NI/s	0.9	1.3	1.7	2.1	2.5
吹气量	m ³ /h	9.2	12.6	16.3	19.0	21.6
A		94				
B		118.5				
C		24.5				
R		G3/8"				
重量	Kg	0.50				
型号		PS 18				
供应压力	bar	1	2	3	4	5
最大吹气压力	-KPa	0.1	0.2	0.3	0.5	0.7
空气消耗	NI/s	1.2	1.7	2.3	2.9	3.6
吹气量	m ³ /h	12.3	17.6	23.0	26.9	31.0
A		94				
B		128.5				
C		34.5				
R		G1/2"				
重量	Kg	0.52				
工作温度	° C	-20 / +60				

注意：以上真空数据为供给压力稳定的情况下获得，且在标准大气压1013 mbar时有效。

供给真空发生器的压缩空气不应润滑，应符合5微米过滤等级，达到ISO 8573-1的4级标准。

换算：N (牛顿) = Kg x 9.81 (重力)；1英寸 = 25.4mm；1磅=453.6克 = 0.4536千克 GAS - NPT螺纹适配接头可见页码 1.134